

# 03-06 MERCEDES BENZ SL500 & SL55 CORE SERVICE BULLETIN



**ATTENTION**



WHEN PREPARING YOUR STRUT FOR RETURN, PLEASE NOTE THAT THE SENSOR MUST BE PRESENT AND INTACT ON THE STRUT. THIS IS AN IMPORTANT COMPONENT OF THE STRUT, AND IS REQUIRED WHEN RETURNING THE CORE FOR A REFUND.

**YOU WILL NOT RECEIVE A REFUND OF YOUR CORE DEPOSIT IF THE SENSOR IS NOT PROVIDED WITH THE STRUT.**

PLEASE REFER TO THE BELOW PICTURE.



THIS MUST BE PRESENT  
ON THE CORE RETURNED

**Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email [techassistance@arnottinc.com](mailto:techassistance@arnottinc.com). (In the EU please call +31 (0)73 7850 580 or email [info@arnotteurope.com](mailto:info@arnotteurope.com))**