



WARNING



INSTALLATION OF THIS AIR SPRING ONTO A DEFECTIVE SHOCK CAN CAUSE DAMAGE AND/OR VOID WARRANTY.

CAUSE: BLOWN SHOCKS

- EXCESSIVE OIL LEAKING FROM TOP OF SHOCK TUBE
- LITTLE OR NO PRESSURE/RESISTANCE FROM SHOCK



**IF EVIDENCE OF A BLOWN SHOCK IS FOUND,
PLEASE REFER TO ARNOTT PART #'S:
REMANUFACTURED: AS-2450, AS-2451, AS-2394 & AS-2463
NEW: AS-2792, AS-2789 & AS-2802
FOR COMPLETE AIR STRUT REPLACEMENTS.**

Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com. (In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com)