Technical Service Bulletins, or TSBs for short, are notifications made directly by manufacturers to help automotive technicians diagnose and repair commonly reported problems. A TSB is issued by Arnott when there is a growing trend with an unanticipated issue that installers need to be made aware of. Arnott Technical Service Bulletins are recommended steps and procedures for specific parts and or components that should be followed to avoid installation problems.

VALVE BLOCK - AIR LINE DIAGRAM

11-17 BMW 5 SERIES GT (F07) 09-15 BMW 7 SERIES (F01/02/04) (FIGURE 1)

NOTE: The colored dots on the valve block match the air line colors.

The colored dots on the valve block



FIGURE 1

14-18 BMW X5 (F15) 15-19 BMW X6 (F16) (FIGURE 2)

NOTE: The colored dots on the valve block are the **opposite** of the air line colors.



FIGURE 2



Arnott US Business Office:

www.arnottinc.com

100 Sea Ray Drive Merritt Island, FL 32953

Call: 800.251.8993

321.868.3016

Fax: 321.868.3703

Email: techassistance@arnottinc.com

Arnott Europe Business Office:

www.arnotteurope.com

Docterskampstraat 1E/1F, 3 5222 AM 's-Hertogenbosch (NL)

NL Phone: +31 73 7850 580

DE Phone: +31 85 2087 438

UK Phone: +44 203 3186 124

BE Phone: +32 258 846 90

ES Phone: +34 91 901 10 56

FR Phone: +32 78 48 46 93

Email: info@arnotteurope.com



Air Springs



Struts



Shocks



Compressors



Dryers



Coil Spring Conversion Kits



Valve Blocks



Ride Height Sensors