

IMPORTANT NOTICE

VALVE BLOCK
AIR LINE DIAGRAM
2011-2018 PORSCHE CAYENNE (92A)
2010-2016 PORSCHE PANAMERA (970)
2016-2020 VOLVO XC90 / 2018-2020 VOLVO XC60



TECHNICAL SERVICE BULLETINS, OR TSBs FOR SHORT, ARE NOTIFICATIONS MADE DIRECTLY BY MANUFACTURERS TO HELP AUTOMOTIVE TECHNICIANS DIAGNOSE AND REPAIR COMMONLY REPORTED PROBLEMS. A TSB IS ISSUED BY ARNOTT WHEN THERE IS A GROWING TREND WITH AN UNANTICIPATED ISSUE THAT INSTALLERS NEED TO BE MADE AWARE OF. ARNOTT TECHNICAL SERVICE BULLETINS ARE RECOMMENDED STEPS AND PROCEDURES FOR SPECIFIC PARTS AND OR COMPONENTS THAT SHOULD BE FOLLOWED TO AVOID INSTALLATION PROBLEMS.



This vehicle contains a "Closed Air Supply System". Replacement of components requires proper adherence to procedures set forth within OE servicing literature. Failure to comply with the OE prescribed procedures can result in component damage and/or failure.

VALVE BLOCK - AIR LINE DIAGRAM

AIR LINE DIAGRAM. (FIGURE 1)




FIGURE 1

SEE REVERSE FOR ADDITIONAL APPLICATIONS

Arnott[®] is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com.

(In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com).

11-TSB31-D REV 03 09/08/2020



IMPORTANT NOTICE

VALVE BLOCK
AIR LINE DIAGRAM
2003-2010 PORSCHE CAYNNE (9PA)
2007-2015 AUDI Q7 (4L)
2004-2010 VW TOUAREG



TECHNICAL SERVICE BULLETINS, OR TSBs FOR SHORT, ARE NOTIFICATIONS MADE DIRECTLY BY MANUFACTURERS TO HELP AUTOMOTIVE TECHNICIANS DIAGNOSE AND REPAIR COMMONLY REPORTED PROBLEMS. A TSB IS ISSUED BY ARNOTT WHEN THERE IS A GROWING TREND WITH AN UNANTICIPATED ISSUE THAT INSTALLERS NEED TO BE MADE AWARE OF. ARNOTT TECHNICAL SERVICE BULLETINS ARE RECOMMENDED STEPS AND PROCEDURES FOR SPECIFIC PARTS AND OR COMPONENTS THAT SHOULD BE FOLLOWED TO AVOID INSTALLATION PROBLEMS.

VALVE BLOCK - AIR LINE DIAGRAM

VEHICLE WILL HAVE MARKED PLATE SHOWING LOCATION OF COLORED AIR HOSE.




FIGURE 1

SEE REVERSE FOR ADDITIONAL APPLICATIONS

Arnott[®] is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com.

(In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com).

11-TSB31-D REV 03 09/08/2020