

REMANUFACTURED AIR STRUT SERVICE BULLETIN



ATTENTION



UPON VISUAL INSPECTION OF YOUR AIR STRUT, IT MAY APPEAR THAT THE AIR STRUT IS BENT. THIS IS COMPLETELY NORMAL AND THE AIR STRUT WILL STRAIGHTEN OUT WHEN PROPERLY INSTALLED ON THE VEHICLE.

DO NOT RETURN AIR STRUT DUE TO THE VISUAL APPEARANCE OF IT BEING BENT.



W220

THIS IS NORMAL
(AS-2193)



W221

THIS IS NORMAL
(AS-2540, AS-2547, AS-2548, AS-2603, AS-2604)



W222

THIS IS NORMAL
(AS-3360, AS-3361, AS-3366, AS-3367)

Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com. (In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com)