




A NEW AIR SUSPENSION COMPRESSOR RELAY IS PROVIDED IN THIS KIT. FAILURE TO REPLACE THIS RELAY WITH THE UNIT PROVIDED CAN CAUSE DAMAGE AND/OR VOID WARRANTY.



RELAY IS LOCATED AT THE FRONT RIGHT-HAND SIDE OF THE LUGGAGE COMPARTMENT

Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com.

(In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com)

1 11-TSB15 REV 2 01/31/2019