

COMPRESSOR SERVICE BULLETIN



ATTENTION




INSTALLATION OF THIS AIR SUSPENSION COMPRESSOR
REQUIRES THE REPLACEMENT OF THE COMPRESSOR RELAY.
**FAILURE TO REPLACE THE OE RELAY WITH THE
UNIT PROVIDED IN THIS KIT CAN CAUSE DAMAGE
AND/OR VOID WARRANTY.**


PLEASE REFER TO YOUR VEHICLE'S SHOP MANUAL OR
CONSULT YOUR LOCAL DEALERSHIP FOR THE LOCATION AND
PROPER PROCEDURES FOR REPLACING YOUR AIR SUSPENSION
COMPRESSOR RELAY.

SEE REVERSE SIDE FOR POPULAR MODELS.


Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com. (In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com)




99-05 Audi A6 allroad quattro (C5)
Relay located on the left side of the vehicle under the dashboard.




99-06 Mercedes-Benz S-Class
Relay located on the right side of the vehicle in the engine compartment.




02-09 Mercedes-Benz E-Class
Relay located on the left side of the vehicle by the firewall.



04-10 Jaguar XJ Series
Relay located on the right side of the vehicle in the engine compartment.



02-09 Audi A8 (w/Gas Engine)
Relay located on the left side of the vehicle under the dashboard.



07-11 Audi A6 (C6)
Relay located on the left side of the vehicle under the wiper cowl.

Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com. (In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com)