




A DEALERSHIP PROVIDED ECU CALIBRATION IS REQUIRED WHEN REPLACING THE AIR SUSPENSION COMPRESSOR. SDD (SYMPTOM DRIVEN DIAGNOSTICS) SCAN TOOL MUST BE LOADED WITH DVD 131.07 CALIBRATION FILE 118, OR LATER.



A NEW AIR SUSPENSION COMPRESSOR RELAY IS PROVIDED IN THIS KIT. REFER TO THE INSTALLATION INSTRUCTIONS FOR RELAY LOCATION AND IDENTIFICATION. FAILURE TO REPLACE THIS RELAY WITH THE UNIT PROVIDED CAN CAUSE DAMAGE AND/OR VOID WARRANTY.



Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com. (In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com)